

**INSPECTION RECORD
F.A.R. 43.11-91.409**

DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE
3-15-01	Hobbs 598.4 Total 598.4	Annual Inspection - Inspected Aircraft I/AW Standardized, Inspected ELT I/AW 91.207(d). Replaced ELT Battery with new next due Apr 2003. C/w SB 53-3159 5 th & 6 th sent Attachment by Installing P/N 36-4012-17 S/N# 779 - see Form 8103-3 in this log. Replaced Induction Air Filter with new. See AD List this log for AD Compliance.
	Tach 598.4 hrs. Total time 598.4 hrs.	I certify this Aircraft has been inspected in accordance with a <u>annual</u> inspection and was determined to be in airworthy condition. Details are on file. Work order No. 201024 Date 3-15-01
		Signed <u>Mark J. Onofri</u> Shop Inspector CARVER AERO, INC. Municipal Airport Davenport, IA 52804 FAA Approved Repair Station No. VRXR118L

**INSPECTION RECORD
F.A.R. 43.11-91.409**

DATE	AIRCRAFT TIME IN SERVICE	KIND OF INSPECTION - STATUS & DISCREPANCY LIST SIGNATURE - CERT. NO. OF PERSON APPROVING OR DISSAPPROVING AIRCRAFT FOR SERVICE
5-1-01	Hobbs 605.9	Reinstalled Repaired SHadin digi data, see Yellow tag this page
	wo# 201024	W/O of Onofri Carver Aero Inc.
3/4/02	Hobbs 735.6 Total 735.6	Completed an annual insp I/AW a standardized annual insp checklist: - C/w ELT. FAR 91.207 (d) - Installed new AC belt - Replaced seals in 1/4 brake caliper - Replaced 1/4 brake lining
	Tach 735.6 hrs. Total time 735.6 hrs.	I certify this <u>airframe</u> has been inspected in accordance with a <u>annual</u> inspection and was determined to be in airworthy condition. Details are on file. Work order No. 201511 Date 3/4/02
		Signed <u>Dawn New</u> Shop Inspector CARVER AERO, INC. Municipal Airport Davenport, IA 52804 FAA Approved Repair Station No. VRXR118L